

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In the Specification.

Please replace the paragraph beginning at Page 9, Line 7 with the following:

After an IPA rinse 310, a chamber part can be blown dry with nitrogen gas N₂. N₂ gas may be an inert gas that is essentially non-reactive to quartz chamber parts and/or the atmosphere. An N₂ blow dry step 312 can accelerate the evaporation of IPA.

RECEIVED
APR 19 2002
TC 1700